

## BOAT DOCK COMMITTEE REPORT

---

### **CURRENT STATUS:**

- Condition of boat docks is good
- Due to lack of rain the lake level is very low
- Water level at inner slips is 2' or less
  - Current Water Level 536.11'
  - This is 1.89' lower than Normal Summer Pool Level
  - This is 17' lower than lake level on 2/26/2019

### **RECENT ACTIVITIES:**

- Most of the dock frame repair work (replacing bolts) was completed on 12/11
- Bubblers were installed before the big freeze in December
- Bubblers are only turned on when temperature and ice risk warrants
- When bubblers are running our monthly electric bill can jump from \$21 to \$350
- All eight bubblers were found to be in good working order
- Two bubblers were purchased in 2006; six bubblers purchased in 2017 or 2018

### **WORK PLANNED FOR SPRING:**

- Replace steel cable on south side of shore bridge
- Replace broken bolts at main dock sections (more involved due to required welding)
- Repair broken frames (requires steel reinforcement and welding)
- Replace rotted finger deck boards
- Add cleats where needed

Submitted by: Mark Fisk and Pete Grogg